


1. Refer to the drawing for the correct identification of the parts of the assembly. 2. Refer to the drawing for the correct identification of the parts of the assembly. 3. Refer to the drawing for the correct identification of the parts of the assembly. 4. Refer to the drawing for the correct identification of the parts of the assembly. 5. Refer to the drawing for the correct identification of the parts of the assembly. 6. Refer to the drawing for the correct identification of the parts of the assembly. 7. Refer to the drawing for the correct identification of the parts of the assembly. 8. Refer to the drawing for the correct identification of the parts of the assembly. 9. Refer to the drawing for the correct identification of the parts of the assembly. 10. Refer to the drawing for the correct identification of the parts of the assembly. 11. Refer to the drawing for the correct identification of the parts of the assembly. 12. Refer to the drawing for the correct identification of the parts of the assembly.



ITEM	PART NO.	QTY	DESCRIPTION
1	419692	1	QUICK DISCONNECT
2	212509	1	ASSY. HOSE; PRESSURE; 108" LONG
3	213709	1	ASSY. HOSE; RETURN; 108" LONG
4	419685	1	PLUG; STRAIGHT; NEOPRENE
5	259611	2	CLAMP; HOSE; #36
6	219500	6 FT.	HOSE; BULK; PROTECTIVE
7	419684	1	PLUG; RUBBER; #10
8	259601	2	CLAMP; CENTER PUNCH; 2-3/4"; STEEL
9	419815	1	BRACKET; MOUNTING; POWER CURBER
10	949808	1	ASSY. HEAD; 2-1/4" SQ. STR; THD: #2500
11	669600	1	NAMEPLATE; WYCO

REV.	DESCRIPTION	DATE	APPROVAL
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			

1. Refer to the drawing for the correct identification of the parts of the assembly. 2. Refer to the drawing for the correct identification of the parts of the assembly. 3. Refer to the drawing for the correct identification of the parts of the assembly. 4. Refer to the drawing for the correct identification of the parts of the assembly. 5. Refer to the drawing for the correct identification of the parts of the assembly. 6. Refer to the drawing for the correct identification of the parts of the assembly. 7. Refer to the drawing for the correct identification of the parts of the assembly. 8. Refer to the drawing for the correct identification of the parts of the assembly. 9. Refer to the drawing for the correct identification of the parts of the assembly. 10. Refer to the drawing for the correct identification of the parts of the assembly. 11. Refer to the drawing for the correct identification of the parts of the assembly. 12. Refer to the drawing for the correct identification of the parts of the assembly.

SECTION A-A
(PARTIAL VIEW)

WYCO A DIVISION OF WYCO INDUSTRIES INC. 1000 WYCO DRIVE WYCO, MISSOURI 64686		DRAWN BY: D. DAVIS, JR. 1/27/70 CHECKED BY: _____ REVISIONS: 949756 DATE: 1/5/70 SCALE: 1:1
NAME: ASSY. HYD. POWERCURBER SIZE: CODE TO NO. PART NUMBER: 949156 D 59980	DATE: 1/5/70 SCALE: 1:1	NAME: _____ DATE: _____ SCALE: 1:1

PART NUMBER 949156